

AOD Safety Inspection Report

Building No: 432

Location: MHATT-CAT, hutches and beamlines, sector 7

Inspected by: Richard Hislop, Elroy, Jeff Alicz, and Dohn Arms and Don Walko

Date Inspected: 9-12-03

Report created by: <u>E. Chang</u>			Date Created: <u>9-14-03</u>	
Safety Issues, Administrative Items, and Miscellaneous				
No.	Description	Specific Location	Owner	Date Completed
1	Reconfiguring laboratory	D020		
2	Reminder: No eating or drinking in laboratory areas	D020		
3	911 sticker for laboratory phone	D030	MHATT-CAT / Elroy	
4	Tool testing needs to be performed on a heat gun	D030	MHATT-CAT / F.C.	
5	Satellite Waste Accumulation Area is being inspected properly – confirmed by Jeff Alicz, CHO	D030	MHATT-CAT	
6				
7				
8				
9				
10				
11				
12				